Compressed Air Entry Kit

Product Numbers
- CAEK

Hardware Pack: none

Required Tools
- Tube Cutter



Insert Termination Plug into the last Air Strip end fitting of the run.



Insert the ½" tube provided into the end fitting of the Air Strip at the beginning of the run.



Cut tube to length if required with the **Tube Cutter**. Push end of tube into straight adapter.



Connect the straight adapter to building air supply, or assemble the ¼" quick disconnect nipple to the straight adapter for source connection.