## Ground Ball

**Product Numbers**
- GBAL6

**Hardware Pack:** none

**Required Tools**
- #2 Phillips Screwdriver




Locate the threaded insert or hole at the center underside of the bottom tube of the UltraFrame. Fasten ring terminal of Ground Ball to frame with a ¼-20x½" Phillips pan head screw using a **#2 Phillips screwdriver**.