ErgoStat Footrest, Glide Base Mount

Product Numbers
- FRE36 thru FRE96

Hardware Pack: FREHP (96100801)

Required Tools
- ⅜" Drill Bit
- Drill
- ½" Wrench or Nutdriver
- ¼" Allen Wrench
- 3/16" Allen Wrench



Drill two ⅜" diameter holes through the side of each glide base at the location shown.



Install a 5/16-18x½" cap screw through the back hole of each glide base and fasten with a 5/16-18 nylock nut on the outward side of the base. Tighten fully with a **¼" Allen wrench** and **½" wrench** or **nutdriver**.



Align holes in end of footrest bar with the front hole in each glide base. Fasten each end with a shoulder bolt and 5/16-18 nylock nut. Tighten fully with a **3/16" Allen wrench** and **½" wrench** or **nutdriver**. Footrest can be rotated forward (shown) or back.