

UTILITY DISTRIBUTOR QUICK DISCONNECT FITTINGS

Quick Disconnect fittings comes factory installed on the Utility Distributor. Additional 1/2" tube (CATK) is needed to connect in-line fittings. The Entry/End Kit (CAEK) is required to connect fittings to shop utilities and terminate the run.

Note: Use the Tube Cutter when cutting the 1/2" tube to assure a proper fit.

To Connect QDs on in-line Utility Distributors

1. Cut the 1/2" tube with a Tube Cutter equal to the distance between adjacent tee adapters of the QD's plus 1". Insert tube into the adapters. Repeat until all QDs in a multiple run are connected.

To Start and Terminate QD with Entry/End Kit

2. Insert Termination Plug into the last tee-adapter in the run.

3. Insert 1/2" tube provided into tee adapter at opposite end of run. Using the Tube Cutter, cut to appropriate length if required. Install NPT adapter on tube end and connect NPT adapter to shop air source.

