

## Surface Leveling Plate


### Product Numbers

- SLPBK


Hardware Pack: n/a

### Required Tools


- 1/8" Drill Bit
- #2 Phillips Screwdriver and/or #2 Phillips Bit
- Cordless Drill/Driver



Install the work surfaces according to surface support instructions. Hold the Surface Leveling Plate on the underside of the work surfaces, centering it over the joint, with a setback of 1/4" from the front edge of the work surface. Mark the hole locations for the plate.



Using an 1/8" **drill bit** and **cordless drill**, drill a pilot hole in each surface at the marked location. Do not drill holes deeper than 1".



Fasten the plate through the pilot holes using two #10-12x1" Phillips flathead screws and a #2 screwdriver/drill with bit.